


# Stage Padding Measuring Guide

Typically stage padding is made in 8' sections with hook and loop attachments to connect sections.

Measurement "A" is the overall length of the stage front to be covered. "B" measurement should be the bottom of the pad to the top edge of the stage (your desired width of the pad). "C" measurement should be the overlap piece that will be attached to the stage area. This measurement should not be included in the "B" total.



$$C + B \times A = \text{Square Foot}$$



Hinge Detail



Artistic Coverings, Inc.  
16444 Manning Way  
Cerritos, Ca 90703  
Toll Free: 877.599.9343  
Local: 562.404.9343  
Fax: 562.404.9335